

## Service Truck Brake Failure Incident

### INCIDENT:

A service truck was reported to have experienced brake failure while being driven down a slope at a mine site. The vehicle veered off the road and came to rest following contact with the safety berm. No injury was sustained by the lone driver in the High Potential Incident (HPI).



Photos of incident site and vehicle involved

### INITIAL OBSERVATIONS:

- Brake failure
- Operator error
- Inadequate Maintenance Management System

**NOTE:** *This safety alert may be displayed at conspicuous places within the project area and the information widely disseminated amongst all concerned.*