



## Contractor Light Vehicle Accident - Multiple Casualties.

### INCIDENT:

A high potential vehicle incident occurred on a mine easement road. The driver of the light vehicle (10-Seater Troop Carrier) lost control and the vehicle whilst travelling downhill turned over and came to rest on its side. There were nine (9) passengers on board; four (4) sustained injuries including the off sider who were on the impact side of the vehicle whilst the driver and the other four (4) were not injured.



### INITIAL OBSERVATIONS:

- Inadequate fatigue management.
- Not driving within speed limits and to road condition(s).
- Lack of proper maintenance system for light vehicle(s).
- Incompetency of driver.
- Inadequate contractor management and supervision.
- Inadequate enforcement of light vehicle policies.

**NOTE:** *This safety alert may be displayed at conspicuous places within the project area and the information widely disseminated amongst all concerned.*